

2019 Construction Season Street Resurfacing Program

Street: Kemmer Lane
Starts: Mercer Avenue
Ends: Snyder Drive

Reasons for inclusion in the Resurfacing Program:

- Poor pavement condition (Rating: 2 out of 10)
- Street initially constructed to now outdated standards. Pavement has extreme failures due to long length of time since initial construction; reconstructing with deeper removal and replacement (Longer term repair)
- Initially paved in late 1960's or 70's (upgrade from a gravel street)
- Unknown exact date of initial construction and there doesn't appear to be a record of any resurfacing according to best available records.

Existing Road Photos:

